EAST Search History

EAST Search History (Prior Art)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1188	73/862.041-862.046. ccls.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/01/07 12:51
L2	130	(yasuji) near3 (ogawa). in.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/01/07 12:52
L3	6	2 and (superimposed)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/01/07 12:52
L4	6	2 and (superimpos$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/01/07 12:54
L5	34	1 and (superimpos$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/01/07 12:55
L6	28	2 and (coil wire)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/01/07 13:03
L7	11	(coil wire) near3 (center $4) near3 (superimpos $4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/01/07 13:07

L8	27	(coil wire) near3 (center $4 central$4) near3 (superimpos$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/01/07 13:07
L12	12624	(coil wire) near3 (center $4 central$4) near3 (superimpos$4 align$4 connect$4 attach$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/01/07 13:12
L13	139	(coil wire) near3 (center $4 central$4) near3 (axis) near3 (superimpos$4 align$4 connect$4 attach$4). clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/01/07 13:13
L14	24	13 and (elastic$4)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/01/07 13:13
L15	23	14 and (load pressure force strain stress)	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2010/01/07 13:13

EAST Search History (Interference)

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L9	27873	(superimpos$4).clm.	USPAT; UPAD	OR	ON	2010/01/07 13:10
L10	2172	9 and (coil wire).clm.	USPAT; UPAD	OR	ON	2010/01/07 13:10
L11	23	10 and (cushion$4). clm.	USPAT; UPAD	OR	ON	2010/01/07 13:10

1/7/10 1:14:18 PM